Certificate Number <<UL-US-L504659-11-12218102-1>> **Report Reference** <<E504659-20181221>> Date 22-Nov-2021 GGM CO LTD Issued to: 180 Oksan-ro Bucheon-si, Gyeonggi-do Republic of Korea 14524 NDMM2 - Incomplete Rotating Machines and Rotating This is to certify that representative samples of Machine Parts - Component See Addendum Page for Product Designation(s). Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety:	UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision Date: 2020-11-05
Additional Information:	See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

an Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/444

Certificate Number Report Reference Date

<<UL-US-L504659-11-12218102-1>> <<E504659-20181221>> 22-Nov-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
K10F(+)200NC-(++)-(+++)	Incomplete Motor Parts
K10F(+)400NC-(++)-(+++)	Incomplete Motor Parts
K10X(+)200N2-(++)-(+++)	Incomplete Motor Parts
K10X(+)400N9-(++)-(+++)	Incomplete Motor Parts
K6F(+)30NC-(++)-(+++)	Incomplete Motor Parts
K6X(+)30N2-(++)-(+++)	Incomplete Motor Parts
K8F(+)60NC-(++)-(+++)	Incomplete Motor Parts
K8X(+)50N2-(++)-(+++)	Incomplete Motor Parts
K9F(+)150NC-(++)-(+++)	Incomplete Motor Parts
K9X(+)100N2-(++)-(+++)	Incomplete Motor Parts

Bandles # Bruce Mahrenholz, Director No



UL LLC

#

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/##

Certificate Number Report Reference Date

<<UL-CA-L504659-31-12218102-1>> <<E504659-20181221>> 22-Nov-2021

Issued to: GGM CO LTD 180 Oksan-ro Bucheon-si, Gyeonggi-do Republic of Korea 14524

This is to certify that representative samples of

NDMM8 - Incomplete Rotating Machines and Rotating Machine Parts Certified for Canada - Component See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety:	CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01, Revision Date: 2017-04-01
Additional Information:	See the UL Online Certifications Directory at https://ig.ulprospector.com for additional information

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

an Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/444

Certificate Number Report Reference Date

<<UL-CA-L504659-31-12218102-1>> <<E504659-20181221>> 22-Nov-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
K10F(+)200NC-(++)-(+++)	Incomplete Motor Parts
K10F(+)400NC-(++)-(+++)	Incomplete Motor Parts
K10X(+)200N2-(++)-(+++)	Incomplete Motor Parts
K10X(+)400N9-(++)-(+++)	Incomplete Motor Parts
K6F(+)30NC-(++)-(+++)	Incomplete Motor Parts
K6X(+)30N2-(++)-(+++)	Incomplete Motor Parts
K8F(+)60NC-(++)-(+++)	Incomplete Motor Parts
K8X(+)50N2-(++)-(+++)	Incomplete Motor Parts
K9F(+)150NC-(++)-(+++)	Incomplete Motor Parts
K9X(+)100N2-(++)-(+++)	Incomplete Motor Parts

S. a mall tor North American Certification Program Bruce Mahrenholz, Director No



UL LLC

#

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/##